



RADON ANALYSIS REPORT

40 Hanlan Road, Suite #45, Vaughan, ON, L4L 3P6 Canada (800) 427-0550

TEST ID NUMBER: 1441680-A1
DATE RECEIVED: 11/15/2022
REPORT DATE: 11/17/2022

DUSTIN BROWN

TEST LOCATION

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon was measured in our laboratory using the liquid scintillation method and the results are reported in Becquerels per cubic metre (Bq/m³). This report will not be released to anyone without your permission except as required by federal, provincial or territorial laws and guidelines.

HERE ARE YOUR TEST RESULTS

<u>VIAL #</u>	<u>ROOM TESTED</u>	<u>DATE OPENED</u>	<u>DATE CAPPED</u>	<u>DATE ANALYZED</u>	<u>RADON LEVEL</u>
4967725	BASEMENT FLOOR LIVING ROOM	Nov 02, 2022 6:57 PM	Nov 04, 2022 8:05 PM	Nov 16, 2022 3:37 PM	192 Bq/m ³
4967718	BASEMENT FLOOR LIVING ROOM	Nov 02, 2022 6:57 PM	Nov 04, 2022 8:05 PM	Nov 16, 2022 3:48 PM	205 Bq/m ³

AVERAGE RADON LEVEL (average result of two tests) : 199 Bq/m³

*This is an amended report to Test ID Number 1441680
*A(n) at the end of Test ID indicates amended report number.

HEALTH CANADA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 200 BECQUERELS PER CUBIC METRE OR HIGHER.

Radon levels less than 200 Bq/m³ still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon levels over a longer period of time. If the radon level is 200 Bq/m³ or higher you should perform either a long-term test or a second short-term test. If you would like to know more about radon mitigation, or have other questions, please call Health Canada at (613) 954-6647 or visit Health Canada's web site at <http://www.healthcanada.gc.ca/radon>.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Jose Figueroa, RMS
NRPP CERT # 109347 RT
NRSB CERT # 18SS007

James E. McDonnell IV